

**B A X I F I R E S D I V I S I O N****ADDENDUM**

This addendum is for the Model 809.

It is possible that during transit the metal disks or 'spinners' located above the bulbs may have become dislodged causing a poor flicker flame effect. In order to relocate the spinners, access them by following the instructions for bulb replacement contained in the installer and owner guide. The 'cap' of the spinner should be located centrally on the pin for best effect.

**BAXI ● VALOR ● WONDERFIRE**

© Baxi Heating U.K. Limited 2006.

**B A X I F I R E S D I V I S I O N****ADDENDUM**

This addendum is for the Model 809.

It is possible that during transit the metal disks or 'spinners' located above the bulbs may have become dislodged causing a poor flicker flame effect. In order to relocate the spinners, access them by following the instructions for bulb replacement contained in the installer and owner guide. The 'cap' of the spinner should be located centrally on the pin for best effect.

**BAXI ● VALOR ● WONDERFIRE**

© Baxi Heating U.K. Limited 2006.

**B A X I F I R E S D I V I S I O N****ADDENDUM**

This addendum is for the Model 809.

It is possible that during transit the metal disks or 'spinners' located above the bulbs may have become dislodged causing a poor flicker flame effect. In order to relocate the spinners, access them by following the instructions for bulb replacement contained in the installer and owner guide. The 'cap' of the spinner should be located centrally on the pin for best effect.

**BAXI ● VALOR ● WONDERFIRE**

© Baxi Heating U.K. Limited 2006.