




Brass full way gate valve with lockshield. XPress ends for copper/carbon steel/stainless steel tube.

GENERAL INFORMATION

Size	Pattern No.	Box Qty	Code	Barcode	Price (£) ex VAT
15mm	PS1068LS	10	203311	5022050224132	£32.02
18mm	PS1068LS	10	203312	5022050224170	£36.06
22mm	PS1068LS	10	203313	5022050224217	£42.78
28mm	PS1068LS	5	203314	5022050224255	£57.76
35mm	PS1068LS	5	203315	5022050224293	£85.46
42mm	PS1068LS	2	203316	5022050224330	£117.57
54mm	PS1068LS	2	203317	5022050224378	£191.31



DIIVIL	JIVOIO	140 ((111111)

Code	Description	A	В	Kg
203311	15mm PS1068LS	98	85	0.38
203312	18mm PS1068LS	98	85	0.38
203313	22mm PS1068LS	104	95	0.56
203314	28mm PS1068LS	117	110	0.87
203315	35mm PS1068LS	130	125	1.30
203316	42mm PS1068LS	141	145	1.62
203317	54mm PS1068LS	165	170	2.84

GUARANTEE

Valves and Fittings

Pegler Yorkshire Customcare 5 Year Guarantee - Terms and Conditions

Products are subject to a 5 year guarantee that is between Pegler Yorkshire and the final purchaser of the product.

The guarantee is subject to proof of purchase being supplied.

This guarantee does not affect any statutory rights the consumer may have in law.

The guarantee covers manufacturing or material defects and does not cover parts subject to normal wear and tear.

This product range has been designed for the use of homeowners, domestic and commercial applications and therefore the guarantee is subject to the product being properly selected for their intended service conditions.

The guarantee is not applicable where the product is fitted contrary to the conditions in the fitting instructions.

This is reinforced where valves are covered by the European Pressure Equipment Directive (PED97/23/EC) where Installation, Operating and Maintenance Instructions are supplied with each product and/or carton.

Provided it is installed correctly and receives adequate preventative maintenance it should give years of trouble – free service.

Abusive behaviour and accidental damage to the product are not covered by this guarantee.

The extent of this liability is limited to the cost of the replacement of the defective item and not to fitting or consequential damages.