



Pegler Yorkshire

PS1070/125LS




Bronze full way gate valve with lockshield. Xpress ends for copper/carbon steel/stainless steel tube.

GENERAL INFORMATION

Size	Pattern No.	Box Qty	Code	Barcode	Price (£) ex VAT
15mm	PS1070/125LS	10	103311	5022050225252	£38.08
18mm	PS1070/125LS	10	103312	5022050225290	£42.12
22mm	PS1070/125LS	10	103313	5022050225337	£57.28
28mm	PS1070/125LS	5	103314	5022050225382	£71.55
35mm	PS1070/125LS	5	103315	5022050225429	£102.04
42mm	PS1070/125LS	2	103316	5022050225467	£137.12
54mm	PS1070/125LS	2	103317	5022050225504	£225.53

DIMENSIONS (mm)



Code	Description	A	B	Kg
103311	15mm PS1070/125LS	98	75	0.39
103312	18mm PS1070/125LS	104	85	0.39
103313	22mm PS1070/125LS	104	85	0.56
103314	28mm PS1070/125LS	117	100	0.84
103315	35mm PS1070/125LS	130	110	1.26
103316	42mm PS1070/125LS	141	130	1.69
103317	54mm PS1070/125LS	165	155	2.67

GUARANTEE

Valves and Fittings

Pegler Yorkshire Customcare 5 Year Guarantee - Terms and Conditions

Products are subject to a 5 year guarantee that is between Pegler Yorkshire and the final purchaser of the product.

The guarantee is subject to proof of purchase being supplied.

This guarantee does not affect any statutory rights the consumer may have in law.

The guarantee covers manufacturing or material defects and does not cover parts subject to normal wear and tear.

This product range has been designed for the use of homeowners, domestic and commercial applications and therefore the guarantee is subject to the product being properly selected for their intended service conditions.

The guarantee is not applicable where the product is fitted contrary to the conditions in the fitting instructions.

This is reinforced where valves are covered by the European Pressure Equipment Directive (PED97/23/EC) where Installation, Operating and Maintenance Instructions are supplied with each product and/or carton.

Provided it is installed correctly and receives adequate preventative maintenance it should give years of trouble – free service.

Abusive behaviour and accidental damage to the product are not covered by this guarantee.

The extent of this liability is limited to the cost of the replacement of the defective item and not to fitting or consequential damages.