




Ballorex Venturi DZR Dynamic Valve - excluding actuator. XPress ends for copper/carbon steel/stainless steel tube. Direct flow measuring.

GENERAL INFORMATION

Size	Pattern No.	Box Qty	Code	Barcode	Price (£) ex VAT
DN15/15mm	PS902SL	1	15282	5022050217875	£260.52
DN15/15mm	PS902SS	1	15283	5022050218087	£260.52
DN15/15mm	PS902SH	1	15284	5022050218162	£260.52
DN15/18mm	PS902SL	1	15285	5022050218216	£261.40
DN15/18mm	PS902SS	1	15286	5022050218278	£261.40
DN15/18mm	PS902SH	1	15287	5022050218322	£261.40

DIMENSIONS (mm)



Code	Description	A	B	C	Kg
15282	DN15/15mm PS902SL	141	76	35	0.62
15283	DN15/15mm PS902SS	141	76	35	0.62
15284	DN15/15mm PS902SH	141	76	35	0.62
15285	DN15/18mm PS902SL	141	76	35	0.62
15286	DN15/18mm PS902SS	141	76	35	0.62
15287	DN15/18mm PS902SH	141	76	35	0.62

GUARANTEE

Valves and Fittings

Pegler Yorkshire Customcare 5 Year Guarantee - Terms and Conditions

Products are subject to a 5 year guarantee that is between Pegler Yorkshire and the final purchaser of the product.

The guarantee is subject to proof of purchase being supplied.

This guarantee does not affect any statutory rights the consumer may have in law.

The guarantee covers manufacturing or material defects and does not cover parts subject to normal wear and tear.

This product range has been designed for the use of homeowners, domestic and commercial applications and therefore the guarantee is subject to the product being properly selected for their intended service conditions.

The guarantee is not applicable where the product is fitted contrary to the conditions in the fitting instructions.

This is reinforced where valves are covered by the European Pressure Equipment Directive (PED97/23/EC) where Installation, Operating and Maintenance Instructions are supplied with each product and/or carton.

Provided it is installed correctly and receives adequate preventative maintenance it should give years of trouble – free service.

Abusive behaviour and accidental damage to the product are not covered by this guarantee.

The extent of this liability is limited to the cost of the replacement of the defective item and not to fitting or consequential damages.